## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


November 25, 2003, PLOOKSAWASDI, S/N not yet assigned Threaded Deformed Reinforcing Bar and Method for Making the Bar Docket No. 25838 Sheet 1 of 6 NATH & ASSOCIATES PLLC, customer no. 20529












November 25, 2003, PLOOKSAWASDI, S/N not yet assigned Threaded Deformed Reinforcing Bar and Method for Making the Bar 'Docket No. 25838 Sheet of 6 NATH & ASSOCIATES PLLC, customer no. 20529






FIG 7

